



Machining

5 Reasons to Keep Machining Coolant Clean

Kip Hanson | Jun 19, 2018

Dirty metalworking fluid can cause a host of problems for your CNC machining operation and can be harmful to machinists—if not cared for properly. Here are the top reasons for keeping your coolant and filters clean and maintained—with advice on how to manage it.

Most machinists would agree that a properly mixed, *high-quality cutting fluid* does smell quite pleasant. But if it is not maintained or cleaned, after awhile, cutting fluid can stink. Give it a couple of weeks of neglect and the Monday morning stench is enough to make even the most olfactory-challenged machinist yearn for the weekend. If the assault on your nose isn't bad enough, however, rancid coolant is hard on other things too, starting with your health—and can negatively affect tool and machine life, finishes and a host of other key metalworking processes and parts.

Here are a few pointers you should keep in mind if you're to optimize productivity while protecting the shop's most important assets: its workers.

Machining Coolant Can Cause Rashes and Dermatitis

To be fair, even freshly mixed cutting fluids contain a host of chemical additives such as biocides, emulsifiers, corrosion inhibitors, anti-foaming agents and more, any of which can cause skin irritation, rashes and dermatitis. When cutting fluid is neglected, the concentration of these chemicals may reach unsafe conditions. Also, an improperly maintained machine tool sump becomes a perfect breeding ground for microbes.

"At low concentrations bacteria can grow unimpeded in the sump and cause pH of the coolant to drop and cause rust," says John Treese, director of global training at Master Fluid Solutions. "Low concentration [of fluid] can grow bacteria that can aggravate skin issues including simple cuts and scratches. High concentration adds too much chemical that can do the same."

Aside from creating noxious odors and degrading coolant, these microorganisms—when combined with tiny skin abrasions—can hasten the chance of infection. "Microabrasions," as they are known in the industry, happen when extremely fine chips and swarf reside in dirty coolant, not so much the larger chips we see flying off the workpiece during the cutting process, explains Jim Brumgard, an application engineer in Castrol's industrial division.

“Of course, big chips can cause cuts, but that type of cut usually requires first aid,” says Brumgard. “The skin abrasions occur when there is coolant splashed onto the skin and then the operator wipes away the dirty coolant ... These often microscopic tiny fines will cause the scratches as the towel or rag is wiping them across the skin.”

They are usually recognized as irritated skin, but what has happened is these tiny cuts have allowed the coolant to cause even more irritation due to broken skin. Bottom line: The dirty coolant has become abrasive to the skin and leaves it more susceptible to irritation, Brumgard asserts.

That’s why coolant should be treated with respect. Wash hands regularly with a mild, nonabrasive soap. Use a moisturizer to create a protective skin barrier that slows the absorption of chemical additives. Wear thin **nitrile gloves** if practical (though never wear heavy gloves around machinery). Keep clothing clean and dry. And avoid using solvents to clean parts, as these eliminate the natural oils on our skin, leaving it unprotected.

Find a Good Sump Pump Doctor

Continuous skimming, monitoring pH and concentration levels, keeping machine tools clean and in top working order—these are all good recommendations that will maximize the life of any metalworking fluid. There comes a time, though, when the machine sump must be removed, cleaned and recharged with fresh coolant. In many shops, this unpleasant task means drawing straws or playing a quick game of rock, paper, scissors to see who gets stuck with the dirty work.

There is a better way. Whether you call it a sump sucker, sump doc, or sump shark, anyone with more than a handful of CNC machine tools should seriously consider investing in one. Instead of slippery floors, chips and rags everywhere, and an hour or two of backbreaking work, sump cleaners are fast and clean. Wheel one of these self-contained units up to the machine, remove the sump’s access panel, and get sucking—15 minutes later and you’re back in business. Some units clean and filter the old coolant as they work, while others are equipped with a “clean side” reservoir containing fresh coolant—either way, sump docs are a smart investment if you’re aiming for the lowest coolant costs and best machining performance possible.

Fine Mists Can Be Harmful to the Respiratory System

Though less noticeable, the delicate tissue lining our lungs is even more susceptible to irritation than our skin. This can be especially problematic at higher spindle speeds, where fine mists are generated and easily inhaled. Unfortunately, the negative health effects connected to mist might not be noticed until years later. No one wants to wear a face mask at work, but if your lathe or machining center isn’t equipped with a properly sized, high-performing air purifier and mist collector, doing so would be an excellent idea, even if you do perform routine cutting fluid maintenance. Clean coolant might smell darned nice, but that doesn’t mean you should inhale it.

Already dealt with the health issues but need some more direct advice on coolant maintenance and

disposal? Read "4 Tips to Optimize Machine Fluid Maintenance and Coolant Disposal."

Be Clean with Machining Coolants And Be Clean with Your Machine

As a rule, water-soluble or "miscible" cutting fluids are fairly alkaline, with a pH of around 8.6 or higher. This helps to prevent corrosion of metal surfaces, keeps microorganisms in check and is a bit easier on human skin. It does, however, tend to eat paint and even rubber seals, especially on older machines not designed with modern cutting fluids in mind. To minimize this, it's a good idea to wipe equipment down before going home at the end of each shift. Regularly inspect seals and wipers for wear and replace as needed. Install a skimmer on each machine to eliminate tramp oil, bacteria's favorite food.

"Tramp oil will slowly dissolve into the coolant, causing it to get thicker and stickier with time," Treese explains. "Bacteria can feed easily on this emulsified tramp oil and then can attack the coolants' oils as well. It is also harder to maintain the proper concentration when the sump is full of chips."

The chips and sludge are displacing coolant, so the volume is ever changing. Keeping the sump clean makes concentration control easier. Monitor pH with a meter (preferred) or test strips weekly—if pH is falling, there's a good chance that something nasty is growing down there. Time to give the machine a thorough cleaning and install some fresh coolant, preferably using a sump doc.

Dirty Coolant Hurts Machine Tool Life and Other Parts of the Machine

Cutting fluids provide lubricity and remove heat from the work zone. As coolant breaks down, the sulfur, chlorine and other extreme-pressure compounds contained within become ineffective. This leads to poor tool and machine life as well as problems with accuracy and part quality.

"Machine tool life suffers when concentrations drop below the coolant manufacturers minimum concentration suggestions and can cause rust on the machine tool," says Treese. "There's just not enough chemical to protect the machine tool."

"Machine life suffers from dirty coolant: That's a true statement," says Brumgard. "Fluid will attach itself to the workpieces, but also to the chips and the dirt, and so you have to monitor coolant for all these things."

But there's more damage that can occur to the machine itself—and to filters and pumps.

"The dirt in your coolant will be abrasive, it will scratch paint, and it will scratch the glazing on a machine's windows inside a newer machine with a cabinet around the workzone," says Brumgard. "The other thing it can hurt and wear out are pumps, especially **high-pressure pumps**, even when they have extra filtration to protect the pump from wear."

So that means there's a cost of changing filters and making sure the filter is changed and not bypassed or ignored, Brumgard explains. Some might think to remove the filter, but then you start to really wearing out costly components. And with through-the-tool coolant delivery holders, you have to pay attention to the rotary coupling's wear, to avoid leakage, Brumgard points out.

It's better to focus on maintaining a clean coolant operation. Here are some ways: Aside from skimming and filtration, cutting fluid concentration should be checked with a refractometer at least weekly, refreshing tired coolant as necessary with properly mixed makeup fluid. One way to accomplish this is with an automatic proportioning unit that sits on the drum, allowing the operator to dial in whatever percentage of fluid is needed to bring the sump back to the correct concentration. If you don't have such a unit, remember the acronym OIL, short for "oil in last," when mixing any cutting fluid. Your cutting tools will thank you.

“Machine life suffers from dirty coolant: That’s a true statement. Fluid will attach itself to the workpieces, but also to the chips and the dirt, and so you have to monitor coolant for all these things.”

Jim Brumgard

Application Engineer, Castrol Industrial

Fluid Maintenance and Disposal Matters to the Bottom Line

Cutting fluid and its disposal are a necessary expense. Though these costs don’t compare to the expense of an idle CNC machine tool, it’s a good idea to maximize coolant life whenever possible. Shops with a few dozen machine tools might consider a centralized cutting fluid system. In lieu of this, a coolant recycling center is probably the best bet, and use a Shop-Vac or sump doc to bring old cutting fluid back to the reservoir for processing.

Here again, maintenance is key. The mantra is: Skim constantly, clean regularly and check religiously. Watch fluid concentrations, using no more concentrate than is necessary but without skimping—as a rule, 10 percent is a good starting point for general-purpose work, although difficult materials such as titanium and superalloys may call for a slightly higher percentage, while aluminum generally cuts best with a leaner mix.

But be careful, warns Treese: “If a manufacturer of *coolant* recommends a 10 percent concentration in the sump, running at 20 percent actually doubles the amount of chemical in the sump—it does not add 10 percent more chemical as some think.”

The water is also important—invest in a deionizer or reverse osmosis system where possible, but do not use softened water. Like Goldilocks, machining operations benefit from cutting fluids that are not too soft, not too hard, but just right.

Do you maintain clean coolant? If not, what challenges do you face in keeping it clean regularly? Share your experience.

www.mscdirect.com/betterMRO

Copyright ©2024 MSC Industrial Supply Co.