

Personal Safety

Some Hazards Aren't Easy To See

3M | Oct 15, 2017

Some hazards are not so easy to see. Some of these hazards include the overexposure to welding fumes such as manganese. Exposure limits for welding fumes can be confusing. Some are set by regulations, and others are advisory. Choosing the correct respiratory protection to protect against these hazards is crucial. The video above explains more about this hidden hazard.

Video Highlights

- Overexposure to Manganese can lead to long term neurologic symptoms.
- Wearing respiratory protection helps protect workers from airborne contaminants, including those you can't see.